


1/12

Fig. 1



10/048165

2/12




Fig. 2

3/12




Fig. 3




Fig. 4



Fig. 5




Fig. 6

Fig. 7





Fig. 8



10/048165

5/12




Fig. 10






Fig. 9

10/048165

6/12



10/048165

7/12




Fig. 13

10/048165

8/12




Fig. 14




Fig. 15

10/048165

9/12




Fig. 16





Fig. 17

10/048165

10/12



11/12





Fig. 21



10/048165

12/12

9500  
CLARKE MFG

Fig. 23





Fig. 24